## **Notice**



CORRECTION PRODUCTION C	CHANGE
SERVICE FLASH ADD INFORMATION	FILE NO.
Please add this notice to the Service Manual listed below.  REVISION 0	
Category: COLOR TELEVISION	Date: NOVEMBER / 01 / 2011
Model:	Effective from : Chassis No. P42841-11
Destination: <u>U.S.A. / CANADA</u> REF : <u>No. SM780194-11</u>	
NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service	
Literature is required. This chassis is similar to Chassis No. P42841-10. Only the	

## SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

difference Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P42841-10 used in

## 1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Model DP42841 (SM780194).

Item No. 088 OP2 Data should be changed from 03h to 04h in the table and in Note 2.

## 2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The are no changes.

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road

Forrest City, Arkansas 72335-2000

DP42841, Z5VK, PRODUCT CODE 113026406

© Sanyo Manufacturing Corporation 2011